


FIG. 1B



100D 



2/9




FIG. 2A




FIG. 2B




FIG. 3




FIG. 4




FIG. 5




FIG. 6

700




FIG. 7

Impact of a Mode Stripper [6umX80um] on a Butterfly MMI Split Ratio




FIG. 8